Woody plants and stands in the health-resort park Brusno, evaluated for quality and quantity

Ľubica Feriancová¹, Roberta Štěpánková²

Department of Garden and Landscape Architecture, Faculty of Horticulture and Landscape Engineering, Slovak Agricultural University in Nitra, 949 01 Nitra, Tulipánová 7, Slovak Republic ¹E-mail: Lubica.Feriancova@uniag.sk, ²E-mail: Roberta.Stepankova@uniag.sk

Abstract

FERIANCOVÁ, Ľ., ŠTĚPÁNKOVÁ, R. 2006. Woody plants and stands in the health-resort park Brusno, evaluated for quality and quantity. *Folia oecol.*, 33: 64–72.

Health-resort parks are an important landscaping element, and, from the very beginning of the modern balneology, they have been embedded naturally into each watering place. The landscape design of the spa park Brusno is a close-to-nature one with minimum presence of regular planting. The park area is approximately 11.5 ha. We have inventoried in total 892 trees and shrubs, 2/3 domestic and 1/3 introduced. In both groups are dominant broadleaved woody plants. The inventory results show that the proposed sanitary cutting (148 woody plants in the park and 99 in the alder stand) is necessary for its successful development. We propose planting of new woody plants as substitution for the plants that do not fulfil their function any more, have not appropriate landscaping value and their presence in the stand is also a security risk. Because the stands mostly consist of domestic woody plants, and the National Nature Protection also requires preserving this character, we recommend to preserve it and, at the same time, to improve its attractiveness, by supplementary outplanting of exclusively domestic woody plants in appropriate shape, colour and growth forms

Key words

spa park, woody plant quality, supplementary outplanting

Introduction

Health-resort parks, an important landscaping element, have been, since the very beginning of balneology, naturally embedded into each watering place. They not only provide a picturesque environment for the spa visitors, but they also contribute to the healing process itself, in an organic, indivisible complexity.

This are the main reasons why it is important to revitalize these objects, to manage them with appropriate and permanent care and to protect them from continuous degradation (SUPUKA, 1991).

The for-long-neglected look of some of these spa parks only emphasizes that the case is naturally urgent. The park in the Brusno Spa can be ranked to such parks. It is a very regrettable fact, because the mineral springs are of unique chemical composition and they also have a specific location. They are far distant from heavy traffic, surrounded by the magnificent nature of the Vepor mountains.

The Brusno Spa is situated in Central Slovakia, in the Horehronie Region, 21 km northeast of Banská Bystrica in the direction to the Brezno town, in a forested lateral valley of the Slovenské Rudohorie Mts., at the foot of the northern slopes of the Vepor Mts. at 435 m asl. The spa lies in a narrow valley called Peklo surrounded by conifer forests. In its southern part, the valley passes to the steep slopes of the mountain massive Vepor. The valley is opened to the north (COLLECTIVE, 1999).

There are several springs of carbonic, hydro-carbonic-sulphatic, calcium-sodium-magnesium containing mineral waters in the spa resort. In terms of climate, the area belongs to the mildly warm and mildly wet area with cold winters. Average temperature in January ranges from -5 °C to -6 °C, in July from 17 °C to 19 °C. The growing season encompasses 200–220 days with an average temperature above 5 °C, 125–150 days with an average temperature of 10 °C and 50–100 days when the average temperature is above 15 °C. The average annual precipitation total is 800–900 mm. The average number of days with snow cover is 80–100. The prevailing winds are western; in winter northwestern, northeastern ones are much less frequent (COLLECTIVE, 1999).

The area of the Brusno spa is embedded into the river-basin of the upper stream of the Hron River. It is situated at the northern edge of Veporské rudohorie Mts. belonging to the widest Slovak mountain range – Slovenské rudohorie Mts. Major part of the area consists of hills with altitude varying from 420 to 860 m asl.

Methodology

Present state of health-resort park

The park, covering an area of about 11.5 ha is comprehended as a natural-landscaping element with minimum regular outplanting. The majority of woody plants is of domestic origin. Introduced woody plants were planted in the most frequently visited parts of park with the purpose of landscaping adjustments. Grassy areas constitute a base for planting of woody plants: solitary, in groups and the youngest in densified stands.

The core of the whole area of the park is an aldertree stand (about 3.5 ha), occupying the central zone characteristic with high level of underground water. Around this central zone, the park and spa buildings have been arranged. The park is surrounded by mostly coniferous stands on slopes of the valley. This forest stand is furthermore surrounded by a closed system of sidewalks, used for access to all its function units. Footpaths are covered with asphalt, currently mostly rather damaged.

The area in front of the treatment facility Pol'ana, at the edge of the alder stand, needs to be adjusted. The area in front of the treatment facility Ďumbier is unsuitable, due to planting without conception. Between the alder stand and the Vepor spring, the Brusnianka brook is crossing the park. Two concrete pools built on the flux offer a very rough and neglected picture.

Plants in all the parts of park reflect the poor level of management. The mobile elements are in a similar state. There are a number of benches spread throughout the park, however absolutely unsuitable for a spa park due to their state and appearance. The same is true ugly waste bins. The lighting badly requires reconstruction, as well.

Natural conditions

The soil cover is the result of former geological conditions and by quarter-geological processes which created substrates of postglacial soils:

- Typical Rendzina, leached, shallow, in a small extent containing debris with prevailing dark calcites and dolomites. They constitute an almost continuous stripe crossing the middle part of the area from southwest towards northeast.
- o Cambisols.

Vegetation conditions are extremely variable, resulting from geographical position, geomorphology, altitude, soil fertility.

Practically the whole area belongs to the zone of the 4^{th} (beech) forest vegetation tier. Marginally present is also the 5^{th} forest vegetation tier – in two small areas (east and southwest part). The 3^{rd} forest vegetation tier is only present in one case, namely in the middle part of the territory.

Evaluation of woody plants inventory

Land area of the surveyed 121,669 m²:

Area A - 10,168 m² Area B - 4,604 m² Area C - 10,594 m² Area D - 11,228 m² Area E - 7,055 m² Area G - 13,944 m² Area H - 9,025 m² Area I - 9,232 m² Area J - 3,273 m² Area K - 35,948 m²

Total $-115,071 \text{ m}^2$.

We have summarized all available published materials, maps, stand descriptions from the forest management plans. The original planting plans are not available. However, some important woody plants could be found on maps with a scale of 1:500, and the patterns were completed in a field survey. We made complete biometric measurements (tree height, diameter $d_{1,3}$, crown width), as well as assessment of the landscape value, health state, damage degree, and we also proposed the modes of treatment. In all areas and stands, there were labelled trees for cutting – a tending intervention with negative selection (removing dead, damaged, disabled woody species, thinning over-dense groups) (SUPUKA and FERIANCOVÁ, 2002).

The inventory was carried out using for-our-purposes-adjusted methodology of woody plants evaluation according to Machovec (1982), Juhásová (1999), and in the forest part of the park (alder stand) according to Saniga and Lukáčik (2000).

In the area, we delineated units – plots marked A– K – for separate evaluation corresponding to the logical and spatial arrangement of the park structure.

Documented data

- 1. Number of the woody plant, identical with the number in the drawing documentation
- 2. Latin and Slovak name

- 3. Form of occurrence:
 - 1 Solitaire tree
 - 2 Shaped solitaire tree
 - 3 Tree in lane
 - 4 Shaped tree in lane
 - 5 Scattered group of trees
 - 6 Connected group of trees
 - 7 Connected group of trees mixed
 - 8 Woodlots outside of forest stand area
 - 9 Natural seeding
 - 10 Solitaire bush
 - 11 Bush in tree understorey
 - 12 Bush in tree lane understorey
 - 13 Scattered group of bushes
 - 14 Connected group of bushes
 - 15 Connected group of bushes mixed
 - 16 Densified group of bushes
 - 17 Riparian stand.
- 4. Tree diameter at a height of 1.3 m above ground was measured with a calliper
- 5. Tree height, measured with an altimeter SUUNTO
- 6. Tree-crown width, the vertical projection of its widest part, measured with a tape, for bushes sqm of the area occupied
- Landscaping value as expression of the woody plant quality. We evaluated the overall aspect, in younger woody plants their ability for further development and suitability for use in composition, suitability for the site or purpose according to the following scale - 5 point scale (MACHOVEC, 1987):

5 – Absolutely healthy woody plant, without damage, habitus corresponding to the species and cultivar, vigorous growth and development. Tree crown representing at least 1/2 of tree height

4 – Healthy woody plant, admitted can be minor damages, shape typical for the taxon, tolerated can be minor irregularities in shape. Good prospect of further existence

3- Woody plant with distorted crown shape, crown relatively short, irregular or untypical. Woody plant mostly healthy or only partially damaged. Requiring adjustment and treatment

2 – Woody plant is shapeless, damaged, deformed, without perspective, detrimental for health, non-aesthetic. Determined to gradual or immediate liquidation (cutting)

1 – Tree or shrub evidently disabled, completely dry or drying out, threatening the safety of pedestrians or traffic, distinctively disrupting composition of alleys or parks. Appointed to immediate cut.

8. The overall health state is, similar to the landscaping value, expressed using a decreasing 5-point scale, assigning to the best quality the highest score of 5 points:

5 – Completely healthy woody plant without signs of diseases, pests and damage

4 – Rare occurrence of diseases and pests, partial wood drying out up to 1/3 of the crown volume, cavities on the trunk rare and small, non-impaired stability

3 – Partial drying or dying of the crown up to 1/2 of its volume due to diseases and pests, medium-size cavities on the trunk caused by wood-destroying fungi or mechanical damage

2 - Diseases, pests or non-biotic elements causing drying out of 2/3 of the volume of the branches, prevailing damage to the main branches, large cavities on the stem, lowered stability caused by decomposition and disintegration of wood by fungi

1 -Totally dry or drying woody plant up to the extent of 2/3 of the crown volume. Extensive cavities and rot on trunk caused by diseases. Stability evidently impaired, wood absolutely unsuitable.

- 9. Type and character of woody plant damage:
 - 1 Stains on leaves caused by microscopic fungi
 - 2 Sufficient callus on wounds after crown trimming
 - 3 Insufficient callus after crown trimming
 - 4 Rot on branching spot
 - 5 Rot on stem
 - 6 Cavity in trunk
 - 7 Deformed woody plant- non-suitable for shaping
 - 8 Low tree stability
 - 9 Non-perspective wood, unsuitably situated
 - **10** Drying out of branches, needles, leaves
 - 11 Trunk and branches infected by fungus
 - 12 Unsuitable, non-proportionally trimmed branches, unsuitably reduced tree-crown
 - 13 Bugs and other pests occurring on leaves
 - 14 Broken and incorrectly treated branches
 - 15 Unsuitably grown tree-crown
 - 16 Trunk shoots
 - 17 Multitrunk
 - **18** *Cameraria ohridella* leaf insect and fungus occurrence on horse chestnut
 - 19 Unsuitable localization of the woody plant
 - 20 Flag-like crown
 - **21** Mechanical damage to the trunk base, caused by mowing.
- 10. Proposed mode of treatment:
 - 1 Trimming and removal of dry and infected branches
 - 2 Trimming of main branches
 - 3 Treatment of wounds
 - 4 Treatment of cavities
 - 5 Covering of cavities
 - 6 Equilibration of the crown (landscaping trimming of crowns)
 - 7 Treatment of wounds caused by broken branches
 - 8 Recovery of old cut wounds

- 9 Treatment of roots
- 10 Removal of parts infected by decay fungi
- 11 Treatment of other infected parts
- 12 Proposal of chemical conservation
- 13 Proposal of cut
- 14 Binding branches in tree-crown
- 15 Immediate trimming of branches (threatening danger of break and fall)
- 16 Lower the tree-crown by trimming the top
- 17 Raking of fallen leaves
- **18** Removal of root shoots
- 19 Removal of trunk shoots
- 20 Maintaining perspective shoots for cultivation
- 21 Removal of natural seeding
- 22 Continual regeneration
- 23 Determining the extent of rot on the stem base
- 24 Hoeing, fertilization
- 25 Transport to more suitable location.

Results

We have pursued inventory on in total 892 woody plants in the park. From this amount, about 2/3 are of native origin and 1/3 are introduced. The majority of both – native as well as introduced, are deciduous woody plants (Table 1). The use of the introduced species can be reasoned with the fact, that they can survive relatively easily and have more attractive habitus. Moreover, the usable portfolio of autochtonous coniferous species and blooming leafy shrubs is rather poor. Despite this, the domestic species should be preferred in outplanting in landscaping and urban context.

Regarding the health state of the inventoried woody plants, we can in general say that it is mostly appropriate (Table 2), in spite of the fact that the basic care is neglected. However, some of inventarized species show signs of damage and diseases indicating unsuitable

| | 1 1 |
|--|--|
| Table 1 Occurrence of woody plants in the spa | nark area according to the origin, native and introduced species |
| ruble 1. Occurrence of woody plants in the spa | park area according to the origin; native and introduced species |

| Native woody plants | Pc | Species | |
|---------------------------------|-----|---|--|
| Coniferous trees | 157 | Larix decidua Mill., Picea abies (L.) H. Karst., Pinus silvestris L., | |
| Broadleaved trees | 389 | Acer pseudoplatanus L., Alnus glutinosa (L.) Gaertn., Betula pendula Roth, Carpinus betulus L., Fraxinus excelsior L., Prunus avium L., Salix alba L., Tilia platyphyllos Scop., Tilia cordata Mill. | |
| Bushes (broadleaved/coniferous) | 77 | Corylus avellana L., Sambucus nigra L., Rosa canina L., Juniperus communis L., Pinus mugo Turra, Taxus baccata | |
| Native total | 623 | | |
| Introduced woody plants | | | |
| Coniferous trees | 95 | Picea omorica (Pančič) Purk., Picea pungens Engelm ., Pinus nigra L., Pseudotsuga menziesii (Mirb.) Franco, Thuja occidentalis L. , Thuja orientalis L., Thuja plicata D. Don ex Lamb., | |
| Broadleaved trees | 124 | Aesculus hippocastanum L., Robinia pseudoaccacia L., Prunus sp., Malus sp., | |
| Coniferous bushes | 22 | Chamaecyparis pisifera Siebold et Zucc. 'Squarosa Aurea', Chamaecyparis lawsoniana Parl., | |
| Broadleaved bushes | 28 | Berberis thunbergii DC. 'Atropurpurea', Chaenomeles japonica (Thunb.) Lindl., Deutzia scabra Siebold et Zucc., Forsythia x intermedia Zabel, Forsythia suspensa Vahl, Ligustrum ovalifolium Hausskn., Philadelphus coro- narius L., Pyracantha coccinea M. Roem., Spiraea x vanhouttei (Briot) Zabel, Swida alba (L.) Opiz, Syringa vulgaris L. | |
| Introduced total | 269 | | |

Species marked in bold are dominant in groups.

Table 2. Evaluation of quality of woody plants and stands

| Eveluated characteristics and factures | | | | | Р | lot | | | | |
|--|------|------|------|------|------|------|------|------|------|-------|
| Evaluated characteristics and features | А | В | С | D | Е | G | Н | Ι | J | Total |
| Number of inventoried woody plants | 110 | 53 | 183 | 82 | 86 | 111 | 139 | 96 | 32 | 892 |
| Average health condition | 3.44 | 3.60 | 3.49 | 3.26 | 3.16 | 3.56 | 3.04 | 2.85 | 3.34 | 3.30 |
| Average landscaping value | 3.45 | 3.47 | 3.60 | 3.40 | 3.39 | 3.59 | 3.07 | 2.85 | 3.31 | 3.34 |

location and conditions for these species. Mass occurrence of *Cameraria ohridella* (insect) was found in all horse chestnut (*Aesculus hippocastanum* L.) exemplars and on rowan trees (*Sorbus aucuparia* L.).

Proposal for the stand recovery (A, B, C, D, E, G, H, I, J parts) is described in Table 3, Appendices 1, 2.

Proposal for the recovery of neighbourhoood of track curve between plots E and D - K / D is seen in Table 4. This part was designed with focussing on the woody plants diversity, vitality of spruce trees and overall improvement of aesthetic effect and balancing of groups of trees and bushes in the composition assembly.

Proposal for the recovery of zone by the brook between plot I and B - K / I is presented in Table 5. Regarding the species, the area is identical with the alder stand K. The plot needs a sanitary cutting. Dry woody plants should be removed and the zone wetted with completed young alder (*Alnus glutinosa* (L.) Gaertn) trees.

Plot K - Alder stand

The alder community is one of the dominant elements of the park. It is situated in a typically wetted site with groundwater ascending to the ground surface. This community plays the key role in this part of the park. Alder is functioning as a so-called "draining pump" which prevents the groundwater soaking through the surface and hampers anaerobic processes on the surface. Fast decaying leaf-litter improves the surface properties of the soil.

The goal of the reconstruction proposed for this stand is to prevent disconnection of crowns of the alder trees. The planned sanitary cutting should improve vitality and increase total volume of tree-crowns in high quality classes. The spots with dead alder trees in which occur anaerobic processes providing conditions for methane creation need to be planted by complementary seeding of this woody plant.

| Table 3. | Proposal | for tree | removal | in | accordance | with | their age |
|----------|----------|----------|---------|----|------------|------|-----------|
|----------|----------|----------|---------|----|------------|------|-----------|

| Park plot | Year | Number of removed trees |
|----------------------|-------|-------------------------|
| Proposal for removal | 2003 | 30 |
| | 2004 | 33 |
| | 2005 | 46 |
| | 2006 | 0 |
| | 2007 | 16 |
| | 2008 | 23 |
| | Total | 148 |

Table 4. The numbers and total volumes of trees determined for removal

| Species in Latin | Species in English | No. | Quantity of timber |
|---------------------------|--------------------|-----|---------------------|
| Pinus sylvestris L. | Scots pine | 1 | 3.25 m ³ |
| Fagus silvatica L. | Beech | 4 | 2.65 m ³ |
| Fraxinus excelsior L. | Ash | 2 | 0.92 m ³ |
| Acer platanoides L. | Norway maple | 1 | 0.11 m ³ |
| Tilia cordata Mill. | Lime tree | 8 | 0.87 m ³ |
| Aesculus hippocastanum L. | Horse chestnut | 1 | 1.71 m ³ |

Table 5. The numbers and total volumes of trees determined for removal

| Species (Latin) | Species (English) | No. | Quantity of timber |
|------------------------------|----------------------|-----|----------------------|
| Alnus glutinosa (L.) Gaertn. | European black alder | 62 | 12.51 m ³ |
| Alnus incana (L.) Moench | White alder | 9 | 1.87 m ³ |
| Salix fragilis L. | Crack willow | 6 | 1.84 m ³ |
| | Total | 77 | 16.22 m ³ |

For the same reason, it is also necessary to complete alder trees on plot I / K. This intervention should improve the aesthetical and functional impact of this part of the park.

The results of the inventory of the woody plants in the health-resort park show that the suggested interventions are crucially important for its development. We especially point out the threat to the *Aesculus hippocastanum* L. species, not by the massively spread *Cameraria ohridella*, a leaf damaging insect, but because the tree trunks are suspected to be attacked by advanced rot. Its extent is to be determined by a phytopathologist. We assume that the extensive hidden rotting can endanger the basic stability of some trees, with regards to their age and health condition. Spontaneous uprooting may occur.

Proposal of new outplantings

The accent on the landscape value of the spa park can be given with an appropriate design of the area between the bathhouse Pol'ana and the alder stand that is at the moment characterized by a ruderal hydrophilous community. Possible solution can be in its extension by an attractive landscape area presenting different growth, shape and colour forms of our native hydrophilous woody plants (trees and shrubs) and permanent herbs – in consistence with a strict landscape style.

Proposal of an additional outplanting of woody plants represents a replacement of those exemplars that ceased to fulfil their function, mostly because of their health state, and as such, they are of unsuitable landscaping value. Their further presence in the stand should threaten the whole area (disrupted stability, negative influence on buildings static, unwanted shadowing, etc.).

The existing stands mostly consist of native woody plants and this trend is to be maintained. The park is to become more attractive, but only with additional outplanting of various shape, colour and growth forms of native species.

Additional outplanting is proposed for the plot "A" – Picea abies 'Inversa', P. abies 'Virgata', Larix decidua 'Pendula', Taxus baccata 'Aurea'.

On plot "B" new outplanting will be provided with cultivars of dwarf pine *Pinus mugo*.

On plot "C" around the water pool with swans, should be planted native willow species *Salix alba 'Tristis'*, *S. caprea, S. cinerea, S. pentadra, S. viminalis*.

Surroundings of the access footpaths contacting plot "K" should be completed with lane outplanting of cultivars of native alders *Alnus incana 'Pendula' and A. incana 'Laciniata'*.

For plot "D" we suggest arolla pine *Pinus cembra* '*Compacta'*, *P. cembra 'Aureovariegata'*, Scots pine

Pinus sylvestris 'Watereri', P. sylvestris 'Fastigiata', P. sylvestris 'Globosa'.

On plot "E" should be completed with missing trees in the maple *Acer platanoides 'Globosum'*. Alley.

On plot "G" add missing pines *Pinus sylvestris* 'Watereri', spruces *Picea abies* 'Nidiformis', *P. abies* 'Remontii'.

On plot "H" we propose the outplanting of a new alley bordering the edge of the alder stand, exclusively with cultivars of *Alnus glutinosa 'Aurea'*, *A. glutinosa 'Pyramidalis'*, *A. glutinosa 'Quercifolia'*, *Alnus incana 'Variegata'*, *A. incana 'Dalecarlica'*, *A. incana 'Coccinea'*.

On plot "I" we propose additional outplanting: by the playgrounds with cultivars of *Sambucus nigra 'Laciniata'*, *S. nigra 'Albovariegata'*, *by the pavilion with cultivars of Taxus baccata 'Aurea'*, *T. baccata 'Dovastoniana'*, *T. baccata 'Adpressa'*.

Along with stand restoration, it is also necessary to rebuild the infrastructure: communications, suitable traffic and ensure new functions appropriately supplementing its purpose.

Conclusions

The above analysis shows that the outplanting of native woody plants is well-reasoned. Their colour, shape and growth aspects can be utilized in pronouncing their environmental impact. The landscaping value of these species has hitherto been severely underestimated, despite of their full adequacy in substituting the introduced ones. For the natural environment of the spa park Brusno which is transcending to the cultural close-tonature landscape, the cultural forms of our native species are especially suitable: namely *Picea abies*, *Sorbus aucuparia*, *Alnus* sp., *Acer* sp., *Salix* sp., *Prunus* sp., *Pinus* sp., *Taxus baccata*.

The health state of the introduced woody plants in the spa park Brusno is evidently worse compared with the native species. It is caused by outplanting them in unfavorable climatic conditions, which is manifested by several frost cracks in tree trunks. It is also worth to mention that their exotic appearance is a strongly disturbing element to the natural character of the spa park (*Thuja* sp., *Chamaecyparis* sp., *Juniperus* sp.,...).

Acknowledgement

This study was financially supported by the VEGA Slovak Grant Agency, projects No. 1/1318/04 and No. 1/1314/04.

References

- JUHÁSOVÁ, G. 1999. Metódy hodnotenia zdravotného a kondičného stavu stromov [Methods for evaluation of health status and condition of trees]. In *Pesto*vanie a ochrana rastlín v mestskom prostredí, ošetrenie chránených a pamätných stromov. Zvolen: Ústav ekológie lesa SAV, 47–60.
- KOLEKTÍV 1999. Aktualizácia kúpeľného lesa Brusno [Innovation of the health-resort forest Brusno]. Zvolen: Lesoprojekt. 68 p.
- LUKAČIK, I. 2000. Premenlivosť, rastová charakteristika a ekológia drevín Alnus glutinosa L. Gaertn., Pinus mugo Turra a Taxus baccata L. v lesných porastoch Slovenska [Variability, growth characteristic and

ecology of Alnus glutinosa L. Gaertn., Pinus mugo Turra and Taxus baccata L. in Slovak forest stands]. Habilitation. Zvolen: Technical University in Zvolen, Faculty of Forestry. 131 p.

- MACHOVEC, J. 1987. *Hodnocení vzrostlé zelene v městských parcích* [Assesment of mature greenery in urban parks]. Životné prostredie, 21 (3): 134–139.
- SUPUKA, J. a kol. 1991: *Ekologické princípy tvorby a* ochrany zelene [Ecological principles for establishment and protection of greenery]. Bratislava: Veda, vydavateľstvo SAV, p. 20–84.
- SUPUKA, J., FERIANCOVÁ, Ľ. 2002. Arborétum Feľaťa vývoj a stav genofondu drevín [Arboretum Feľaťa – development and state of the gene pool of woody plants]. *Folia oecol.*, 29 (1-2): 9–29.

Kvalitatívne a kvantitatívne hodnotenie drevín a porastov v kúpeľnom parku Brusno

Súhrn

Kúpeľné parky tvoria významný krajinotvorný prvok a od počiatkov moderného kúpeľníctva sú neodmysliteľnou súčasťou každého kúpeľného miesta. Vytvárajú pre návštevníkov kúpeľov nielen malebné prostredie, ale svojimi vlastnosťami sa priamo podieľajú na liečebnom procese. Kúpele v Brusne sú špecializované na liečenie žlčníka, žlčových ciest a pečene, keďže ako jediné na Slovensku majú na to minerálnu vodu vhodného chemického zloženia.

Kúpeľný park je riešený v prírodne krajinárskom slohu s minimálnym zastúpením pravidelných výsadieb na ploche cca 11,5 ha. Bolo tu zinventarizovaných celkom 892 drevín. Z toho je približne 2/3 domácich a 1/3 introdukovaných. U domácich aj introdukovaných prevládajú listnaté druhy.

Z výsledkov inventarizácie je zrejmé, že bez odporúčaných zásahov (výrub 148 drevín v parku a 99 v jelšovom poraste) nie je možné počítať s jeho perspektívnym rozvojom.

Návrh nových výsadieb drevín predstavuje náhradnú výsadbu za dreviny, ktoré najmä zo zdravotného hľadiska prestali plniť svoju funkciu, majú nevyhovujúcu sadovnícku hodnotu a ďalším zotrvaním v poraste sú rizikovými drevinami z hľadiska bezpečnosti.

Keďže porasty sú prevažne domáceho pôvodu a tento charakter aj vďaka záujmom štátnej ochrany prírody je žiaduce zachovať, ako aj kvôli zatraktívneniu parku, všetky doplňujúce výsadby drevín navrhujeme z tvarových, farebných a vzrastových foriem iba autochtónnych (domácich) druhov drevín.







Appendix 2